

18 July 2018

MC850 Control and Reporting Software v1.0.3.4 Release Notes

Issues fixed

1. Under certain operating system configurations, the entry box for the 4 octets of the fixed IP address, subnet mask, and default gateway, only displayed 3 octets, and did not allow entry of the 4th octet.
2. The power allocation configuration group was not displayed for the MXZ model only.

MC850 Firmware v046 Release Notes

Issues fixed

If the amplifier was in standby mode or sleep mode, the load test returned erroneous values. Now the command returns an error code under these conditions.