



## Maintenance Release

Issues resolved in DSPCC Software Version 3.6.0

Release Date April 12, 2017

Issue #	Description
DSPCC-23	The ducker display window cut off channel 7 and 8 meters.
DSPCC-24	It was possible to start multiple simultaneous upload/download processes by clicking the OK or Refresh button several times while data was being transferred between the device and Control Center. This resulted in corrupt data and unpredictable behavior.
DSPCC-27	DSPCC was not properly saving configuration files (.scfg), and consequently files were not properly loaded. This affected filters on network input channels and local output channels on some models.
DSPCC-28	DSPCC was not always sending updates from the GUI to the device when connected. This caused the GUI and the device to be out of sync under certain conditions.
DSPCC-29	DSP-enabled amplifier models appearing in the launch dropdown list were renamed and reordered for consistency and convenience.
DSPCC-30	Restore Default Settings feature added under the File dropdown menu.